OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-360

Manufacturer Name: Mercedes-Benz USA, LLC

Submission Date: JUN 12, 2023 **NHTSA Recall No.:** 23V-360 **Manufacturer Recall No.:** 2023060004



Manufacturer Information:

Manufacturer Name: Mercedes-Benz USA, LLC

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

Population:

Number of potentially involved : 7,558 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2022-2022 Mercedes-Benz EQS 450

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : NR

Descriptive Information: Mercedes-Benz Model Year 2022 ESQ 450 4285 vehicles. The recall population was

determined through potentially affected software versions. Vehicles outside of the recall population have software that meets the current production specifications.

Production Dates: APR 20, 2021 - FEB 27, 2023

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2022-2022 Mercedes-Benz EQS 580

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : NR

Descriptive Information: Mercedes-Benz Model Year 2022 ESQ 580 2522 vehicles. The recall population was

determined through potentially affected software versions. Vehicles outside of the recall population have software that meets the current production specifications.

Production Dates: APR 20, 2021 - FEB 27, 2023

Vehicle 3:	2023-2023 Mercedes-Benz Maybach S 580			
Vehicle Type :	LIGHT VEHICLES			
Body Style :	4-DOOR			
Power Train :	GAS			
Descriptive Information :	Mercedes-Benz Model Year 2023 Maybach S 580 125 vehicles. The recall population was determined through potentially affected software versions. Vehicles outside of the recall population have software that meets the current production specifications.			
Production Dates :	APR 20, 2021	- FEB 27, 20	23	
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential
	LIGHT VEHICE 4-DOOR GAS Mercedes-Ber	LES	z Maybach S 680 r 2023 Maybach S 680 138	vehicles The recall population
Production Dates : VIN Range 1 :	the recall pop APR 20, 2021	ed through p ulation have	ootentially affected software software that meets the cu	e versions. Vehicles outside of rrent production specifications.
VIN Range 1: Vehicle 5: Vehicle Type: Body Style: Power Train:	the recall pop APR 20, 2021 Begin: 2023-2023 M LIGHT VEHICH 4-DOOR HYBRID ELECT Mercedes-Ber determined th	ed through pulation have - FEB 27, 20 NR ercedes-Ben LES TRIC nz Model Yeanrough poter	cotentially affected software software that meets the cu 23 End: NR z S 580e r 2023 S-Class 580e 488 ventially affected software ventices.	e versions. Vehicles outside of rrent production specifications.
VIN Range 1: Vehicle 5: Vehicle Type: Body Style: Power Train:	the recall pop APR 20, 2021 Begin: 2023-2023 M LIGHT VEHICH 4-DOOR HYBRID ELECT Mercedes-Berdetermined the recall population	ed through pulation have - FEB 27, 20 NR ercedes-Ben LES TRIC nz Model Yea nrough poter ion have soft	cotentially affected software software that meets the current software that meets the current software vertware vertware that meets the current software vertware vertwar	e versions. Vehicles outside of rrent production specifications. Not sequential Phicles. The recall population was rsions. Vehicles outside of the

Description of the Defect: Mercedes-Benz AG has determined that on certain S-Class (223 platform) and

EQS (297 platform) vehicles, the monitoring software of the Electronic Stability

Program ("ESP") might not meet current production specifications.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Under certain conditions, the ESP monitoring software could erroneously

determine a fault condition. In that event, the ESP fault response would limit the functionality of the vehicle's dynamics control systems (ABS, ASR, ESP, and EBD) and the speedometer would indicate a speed of 0 mph (0 km/h), regardless of the actual vehicle speed. These might increase the risk of a

crash.

Description of the Cause: Due to a deviation in the ESP monitoring software, internal monitoring

routines may erroneously identify a failure condition at the beginning of a driving cycle, which would limit the functionality of the ESP system during

vehicle operation.

Identification of Any Warning Before the issue occurs, the driver would not receive an advance warning due

that can Occur: to the nature of the failure mechanism.

When the issue occurs, various warning messages and warning lamps would be

shown in the instrument cluster to alert the driver.

Involved Components:

Component Name 1: ESP Software **Component Description: ESP Software** Component Part Number: A 223 902 06 22

Supplier Identification:

Component Manufacturer

Name: Robert Bosch GmbH (Blaichach Plant)

Address: Robert-Bosch-Strasse 1

Immenstadt Foreign States 87509

Country: Germany

Chronology:

In January 2022, MBAG investigated an individual field report claiming that a vehicle lost functionality of its dynamic control systems (including its anti-lock brake system, acceleration slip regulation, and electronic brake force distribution) and speedometer during operation. MBAG requested parts from the affected vehicle for further analysis.

MBAG began its analysis of the affected vehicle by focusing on the ESP pump motor. At that time, MBAG hypothesized that this component may be the source of the reported issues based on diagnostic data from the vehicle and review of the conditions that trigger this diagnostic code. That investigation did not reveal any defect in the vehicle's ESP pump motor and did not identify a failure mechanism.

MBAG conducted further investigations between February and April 2022 using simulations of field conditions that it suspected could trigger the reported failure. Based on these tests, MBAG determined that certain driving conditions could interfere with routines executed by the ESP monitoring software at the beginning of each driving cycle. It was concluded that this interference could lead to an erroneous detection of a fault condition of the ESP pump motor power supply.

Beginning in July 2022, to address this potential error, MBAG developed and tested an ESP software update.

At the end of 2022, MBAG conducted a general internal review of factors affecting the function of the ESP system as well as how such issues are classified and managed. Based on this review, in January 2023, MBAG commenced analyses to determine if there were potential safety consequences of an erroneous detection of a fault condition of the ESP pump motor power supply.

As part of this review, during March and April 2023, MBAG and its supplier, conducted driving tests to determine the potential impacts of the subject fault condition on vehicle performance (especially ESP and other dependent systems). Please see the Chronology Supplement.

Description of Remedy:

Description of Remedy Program: An authorized Mercedes-Benz dealer will update the ESP control unit

software on the potentially affected vehicles.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described

and all remain covered under the new vehicle warranty.

How Remedy Component Differs The ESP control unit software meets the current production specifications.

from Recalled Component: Remedy Parts:

A 223 902 61 23 (ESP software) A 214 902 58 01 (ESP software)

Identify How/When Recall Condition The series introduction of a new ESP software version ensured that this

was Corrected in Production: issue would not occur after May 01, 2023.

Recall Schedule:

Description of Recall Schedule: Dealers will be notified of the pending voluntary recall campaign on

March 26, 2023. Owners will be notified of the voluntary recall campaign before July 18, 2023. A copy of all communications will be provided when

available.

Planned Dealer Notification Date: MAY 26, 2023 - NR Planned Owner Notification Date: JUL 18, 2023 - NR

* NR - Not Reported