OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

23V-159

Manufacturer Name: Rivian Automotive, LLC

Submission Date: MAR 09, 2023 NHTSA Recall No.: 23V-159 Manufacturer Recall No.: FSAM-1185



Manufacturer Information:

Manufacturer Name: Rivian Automotive, LLC

Address: 13250 North Haggerty Road

PLYMOUTH MI 48170

Company phone: 999

Population:

Number of potentially involved: 30 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2022-2023 Rivian R1S

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : NR

Descriptive Information: Certain 2022 and 2023 R1S vehicles.

The potentially affected vehicle production began on October 28, 2022, when Rivian Automotive, LLC ("Rivian") started to build vehicles with the suspect side curtain airbag fastenings and ended on January 21, 2023, when Rivian stopped building with

the suspect fastenings. The suspect population was determined using Rivian

manufacturing records.

Production Dates: OCT 28, 2022 - JAN 21, 2023

VIN Range 1: Begin: NR End: NR

Description of Defect:

Description of the Defect: One or more of the fasteners that secure the right or left side curtain airbag to

the vehicle may be improperly fastened.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the side curtain airbag is not properly secured to the vehicle, the airbag

may not perform as intended and increase the risk of injury in certain crash

conditions.

Description of the Cause: NR Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NUT

Component Description: M6X1.0 HX WSHR CON NYL CL8 R102C

Component Part Number: SC00007247-A, SC00007247-B

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

On February 16, 2023, Rivian identified a vehicle at the Normal vehicle assembly plant in which some of the side curtain airbag fasteners did not properly secure the airbag to the roof rail. The vehicle was inspected and an investigation into root cause and scope was initiated.

The investigation concluded on March 1, 2023. Rivian's manufacturing data analysis identified 30 potentially affected vehicles.

On March 2, 2023, Rivian determined that a safety-related defect exists related to this matter.

As of the date of this filing, Rivian has not identified any field reports or warranty claims potentially related to this issue in any market.

As of the date of this filing, Rivian is not aware of any crash, death, or injury reports related to this issue in any market.

Description of Remedy:

Description of Remedy Program: Rivian will inspect and, as necessary, properly secure the side curtain

airbag fasteners in the affected vehicles. In the unlikely event that components require replacement, Rivian will replace components, as

necessary.

Rivian has a policy and practice of reimbursing owners who have paid for a repair that subsequently becomes the subject of a field action. To ensure consistency, Rivian, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the

company for confirmation of the expense.

from Recalled Component:

How Remedy Component Differs The remedy components will be properly secured fasteners, as necessary.

Identify How/When Recall Condition NR was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: For any owners not contacted, we will mail notifications on or before

April 28, 2023. Rivian began telephoning customers on March 2, 2023. As a direct-to consumer manufacturer, Rivian owns and operates all of the Company's sales and service operations. As all "dealers" are Rivian owned entities, notification will be through internal means to our licensed store and service operations addressing this recall on or before

the date set forth in this response.

Planned Dealer Notification Date: APR 28, 2023 - APR 28, 2023 Planned Owner Notification Date: APR 28, 2023 - APR 28, 2023

^{*} NR - Not Reported